



SPECIFY CATALOG NO. AND SERIAL NO. WHEN ORDERING PARTS			REVISED BULLETIN	DATE
O.E.M. CHARGER				May '99
CATALOG NO. 48-59-0125	SERIAL NUMBER	966A	WIRING INSTRUCTION	

00 0

EXAMPLE:
Component Parts (Small #) Are Included
When Ordering The Assembly (Large #).



WARNING
Handle circuit board with care.
High voltage, 191 VDC, may
be present at C19 and could
result in a shock.

FIG.	PART NO.	DESCRIPTION OF PART	NO. REQ.
1	06-82-9207	6-32 x 11/16" Pan Hd. Slit. PT T-10	(4)
2	22-64-1051	Cordset	(1)
★3	23-28-0100	Light Pipe	(2)
4	12-20-0195	Service Nameplate Kit	(1)
5	-----	Circuit Board Assembly	(1)
6	-----	Battery Contact	(3)
★7	31-50-1395	Upper Housing - Service	(1)
8	31-50-1356	Lower Housing	(1)

- FIG. NOTES**
- 5 Circuit board assembly to be fully seated on the lower housing screw bosses so that the top of the boss is flush with, or above, the top of the circuit board assembly.
 - 2 Cordset terminals to be fully seated on their mating terminals and separated from one another by a minimum of .125".
 - 7, 8 Verify that the top housing is fully seated on the lower housing prior to installing the screws.