SERVICE PARTS LIST


Milwaukee

SPECIFY CATALOG NO. AND SERIAL NO. WHEN ORDERING PARTS REVISED BULLETIN DATE Dec. 2006 **MULTI-VOLT CHARGER** WIRING INSTRUCTION SERIAL NUMBER 48-59-2818 CATALOG NO. **A96A A96B**

EXAMPLE:

 $00|_{\overline{0}}$

Component Parts (Small #) Are Included When Ordering The Assembly (Large #).



J2 J2	J5 J3 D
	J4 A BLACK
FIG. PART NO.	DESCRIPTION OF PART Top Housing

D

BLACK(E

			l
FIG.	PART NO.	DESCRIPTION OF PART	NO. REQ.
1		Top Housing	(1)
2		Bottom Housing	(1)
3		PCB Assembly	(1)
4	22-64-1150	Cordset	(1)
5		Screw	(4)
6		Screw	(4)
7		Battery Connector Assembly	(1)
8		Logo Label	(1)
9		LED Lens	(1)
10	12-20-1705	Service Nameplate	(1)
r 11	10-20-0895	Warning Label	(1)
12		Rubber Bumpers	(4)

FIG.

(12)

- 3,4 Cord set terminals are to be fully seated on mating terminals of printed circuit board assembly and perpendicular to printed circuit board surface.
- 2,4 Cord set to be free from conductor twists and cord crossover prior to installation of strain relief into bottom housing.

MILWAUKEE ELECTRIC TOOL CORPORATION 13135 W. LISBON RD., BROOKFIELD, WI 53005