



**BOSCH**

# Drill

GBM 13 | 3 601 D77 082

---

## Table of Content

Spare parts list.....	2
Illustration - Type.....	3

## Spare parts list

Item	Part Number	Description
1	2 609 100 642	Housing BLUE
2	1 619 P21 238	Field 230V
4	1 607 200 508	On-Off Switch BLACK
5	2 604 460 245	Power supply cord CN 220V 2,65m 2 x 0,75mm H05 VV-F
6	2 600 707 059	Grommet Ø6,9 MM
13	2 609 110 153	Ball Bearing 8x22x7
14	2 609 110 491	Ball Bearing
16	2 609 120 356	Brush Plate
19	2 603 490 022	Screw 4x16
29	1 900 210 000	O-Ring 5,0x1,5 MM
33	2 609 110 719	Ball Bearing
34	2 609 199 158	Bearing Bracket
43	2 609 110 709	Cylindrical Gear
803	1 619 P20 872	Armature set 220
810	2 610 391 290	Carbon-Brush Set
841	2 609 120 407	Spindle Assembly
846	1 608 571 080	Key Chuck Ø1,5-13 MM
846	2 608 571 076	Chuck
847	2 607 950 007	Chuck Wrench SG2

Illustration - Type - E

3 601 D77 080  
 Stand | 12-08  
 Issue | 15-05-13

Fig./Abb. 1

