



**BOSCH**

# Drill

GBM 350 RE | 3 601 A3A 743

---

## Table of Content

Spare parts list.....	2
Illustration - Type.....	3

## Spare parts list

Item	Part Number	Description
1	2 609 100 181	Housing Section
2	1 619 P20 880	Field
4	2 607 200 623	Switch
5	1 604 460 274	Power supply cord CN 220V 2,15m 2 x 1,0mm H05VV-F
6	2 600 707 059	Grommet Ø6,9 MM
7	2 601 035 001	Cable Clip
9	2 609 130 468	Manufacturer's nameplate
13	2 600 301 068	Sintered-Metal Bushing
14	1 619 P06 024	Ball Bearing
15	2 609 110 019	Pressure Plate
16	1 619 P20 806	Brush Holder
19	1 619 P00 228	Screw
28	1 619 P00 219	Tapping Screw
31	1 903 230 009	Ball DIN 5401-5 G28
33	1 619 P20 250	Adjusting Slide
44	1 619 P00 478	Bushing
45	1 619 X07 256	Ball Bearing
46	1 608 571 079	Chuck Ø1,0-10 MM, 3/8"
46/7	2 607 950 007	Chuck Wrench SG2
47	1 619 P00 229	Plain Washer
803	1 619 P20 807	Armature set
804	1 619 P20 808	Switch Set
808	1 619 P20 805	Nameplate
810	1 619 P20 809	Carbon-Brush Set
841	1 619 P00 079	Drilling Spindle
844	1 619 P00 467	Housing Set

Illustration - Type - E

0 601 13A 707

Stand | D7-11  
Issue | 20-09-10

Fig./Abb. 1

■ = 804 = Typ 703 ; 706 ; 707 ; 708 ; 740 ; 743

