



Position	Amount	Type number	Description	PG
1	1	316062290	Armature compl., 120V	37
2	1	311012240	Feldpaket vollstaendig	28
3	1	344492750	Cable with UL-CSA-plug	23
4	1	344100970	Cable sleeve	12
5	1	343362490	Cable clip	12
6	1	141117060	Self-tap. fill. h. screw	12
7	2	344498880	Strand compl.	11
8	1	315013660	Motor housing	22
9	1	316053640	Shift lever compl.	17
10	1	343437890	Pivoting switch	11
11	1	143115690	Ball bearing,6x19x6	13
12	1	344097870	Rubber bushing	11
13	1	343436590	Baffle	13
14	1	143114880	Ball bearing, 8x22x7	14
15	1	343433770	Motor cap 2 part	19
16	3	141113180	Self-tap. fill. h. screw	11
17	4	141117060	Self-tap. fill. h. screw	12
19	1	315202620	Bearing flange	25
20	1	344160400	Open-end spanner	16
22	1	344099150	Handle	19
23	1	316051730	Spindle head compl.	38
24	1	343082850	Electronic unit,120V	31
25	1	343409640	Switch	19
26	2	316045980	Brush holder compl. cut out	21
27	1	316046900	Carbon brush set cut-off	22
29	1	630821000	Collet 1/4" with flange nut(double flat)	
30	1	316062270	Carrier cpl.	24
31	1	344099140	Buffer	13
35	1	338062530	Rating plate	11
36	1	338122090	Warning Label 52x22	11
61	1	316065220	Spindle head compl.	33
62	1	143115930	Ball bearing,	19
63	1	143111090	Ball bearing, 10x30x9	24
64	1	141180370	Retaining ring	11
65	1	143115490	Compensating washer	11
66	1	341071300	Coupling	18
70	1	143115470	Compensating washer	11
71	1	316051700	Luefter mit Staubschutzkorb	17
75	1	316059800	Spindle lock	21
80	1	330002060	Fan	14
98	2	143195530	O-ring	11

Position	Amount	Type number	Description	PG
1001	1	338505710	Wiring diagram	

