



BOSCH

Straight Grinders

GG5 5000 L | 3 601 B24 181

Table of Content

Spare parts list.....	2
Illustration - Type.....	4

Straight Grinders | GGS 5000 L | 3 601 B24 181

Spare parts list

Item	Part Number	Description
1	1 619 P11 358	Motor Housing
3	1 619 P08 212	Armature 220-240V
3/50	1 606 610 141	Fan
4	1 607 200 179	On-Off Switch
5	1 604 460 263	Power supply cord H05 W-F CN 2,65m 2 x 0,75mm
6	2 600 703 012	Grommet Ø6,5-Ø6,9x95 MM
7	1 601 302 017	Fastening Clamp
12	1 619 P09 448	Suppression Filter
13	1 619 P08 829	groove ball bearing
14	1 619 P00 455	Ball Bearing
16	1 619 P01 811	Brush Holder
17	1 604 652 013	Spiral Spring
18	1 604 611 031	Compression Spring
21	1 619 P10 235	Spindle Housing
22	1 602 319 009	Adjusting Slide
23	1 619 P02 762	Switch Button BLACK
24	1 600 502 023	Intermediate Ring
25	1 619 P09 255	Housing Cover BLUE
26	1 619 P09 256	Intermediate Flange
27	1 619 P09 261	Retaining snap ring
28	1 619 P09 434	Sleeve Ring
30	1 619 P09 263	Connector
32	1 619 P09 262	Adjusting Ring
39	1 619 P11 770	Cap Nut
40	1 619 P09 863	Protective Sleeve
42	2 609 110 052	Special Screw
43	1 619 P00 220	Torx Oval-Head Screw 3x10
45	2 910 611 020	Tapping Screw DIN 7981-ST3,9x19-C-H
46	1 619 P09 269	Torx Oval-Head Screw
650/1	1 619 P09 252	Lock nut
650/2	1 619 P10 661	Collet
802	1 619 P09 888	Field 230V
810	1 607 014 145	Carbon-Brush Set
829	1 619 P09 921	Air-Deflector Ring

Spare parts list

Item	Part Number	Description
833	1 619 P09 253	Spindle Assembly

Illustration - Type - E

3 601 B24 081
Stand } 15-11-13
Issue } 15-11-27

Fig. /Abb. 1

Gerat - Verzahnung

• Vor Demontage des Ankers
Kohlebürsten 5mm zurückziehen !
Before the armature is removed the carbon brushes
must be withdrawn by at least 5mm !

