



BOSCH

Percussion Drill

GSB 13 | 3 601 B27 080

Table of Content

| | |
|--------------------------|---|
| Spare parts list..... | 2 |
| Illustration - Type..... | 3 |

Spare parts list

| Item | Part Number | Description |
|------|---------------|---|
| 1 | 2 609 100 961 | Housing |
| 2 | 2 609 120 588 | Stator 230V |
| 4 | 1 607 200 508 | On-Off Switch BLACK |
| 5 | 2 604 460 245 | Power supply cord CN 220V 2,65m 2 x 0,75mm H05 VV-F |
| 6 | 2 600 707 059 | Grommet Ø6,9 MM |
| 7 | 2 601 035 001 | Cable Clip |
| 13 | 2 609 110 153 | Ball Bearing 8x22x7 |
| 14 | 2 609 110 491 | Ball Bearing |
| 16 | 2 609 199 416 | Brush Plate |
| 19 | 2 603 490 022 | Screw 4x16 |
| 24 | 2 609 110 537 | Clip |
| 26 | 2 600 590 006 | Ratchet Cap |
| 30 | 2 609 110 922 | Pressure Plate |
| 31 | 2 609 100 728 | Shift Lever |
| 32 | 1 903 230 010 | Ball DIN 5401-5,5MM-III-ST |
| 33 | 2 600 905 068 | groove ball bearing 15x32x9 |
| 34 | 2 609 199 228 | Bearing Bracket |
| 39 | 2 609 000 990 | Key Chuck |
| 41 | 2 604 616 006 | Compression Spring |
| 654 | 2 609 199 582 | Auxiliary Handle |
| 655 | 2 609 005 615 | Depth-Gauge |
| 803 | 2 609 199 667 | Armature set 230V |
| 810 | 2 610 391 290 | Carbon-Brush Set |
| 835 | 2 609 199 665 | Gear Housing |
| 836 | 2 609 199 666 | Spindle Assembly |
| 839 | 2 607 950 007 | Chuck Wrench SG2 |

Illustration - Type - E

3 601 B27 180
 Stand } 14-82
 Issue } 16-01-12

Fig./Abb. 1

