


IMPORTANT — To assure product **SAFETY** and **RELIABILITY**, repairs, maintenance or adjustments should be performed by **MAKITA** Service Centers or other qualified service organizations. Always use **MAKITA** replacement parts.


SERVICE CHANGE

- 1) Change on Ball Bearing 606ZZ from serial number 5598E.

TYPE 1



TYPE 2



Always install the block so that the groove on it faces the gear housing cover.

FIG.	DESCRIPTION	TYPE 1	TYPE 2
40	_____	Part #211012-0 Ball Bearing	Part #331464-0 Block
41	Thin Washer 6	Part #253308-3	_____

The above parts are completely interchangeable as a set.