



Position	Amount	Type number	Description
1	1	341703790	Cap screw
2	1	341031860	Clamping flange
3	1	341031870	Clamping flange
4	4	341703840	Tap tite screw TORX 20 x 10
5	1	339132120	Retraining sheet
6	1	315417280	Pendulum guard
7	1	315417270	Saw housing
8	1	341703810	Countersunk screw
9	1	339040870	Rubber ring
10	1	315417130	Saw housing
11	3	141120070	Fill. head screw(DIN 7985)
12	2	141130650	Hexagonal lock nut
13	1	316044990	Spindle lock
14	1	342003230	Pressure spring
15	1	316038050	Gear-box cpl.
16	1	342003310	Pressure spring
17	1	343397750	Switch-on lock
18	1	343408810	Electronic switch,DC 18V
19	1	316038060	Gear-box cpl.
20	4	141116990	Self-tap. fill. h. screw
21	1	343397740	LED
22	1	315013380	Motor housing
23	10	141118730	Self-tap. fill. h. screw
24	1	338121830	Metabo label 40x14 ULA 14.4-18
25	5	141120340	Screw
26	1	343398010	Motor cover
27	4	141120470	Self-tap. fill. h. screw
28	1	338052190	Rating plate
29	1	141119480	Fill. head screw(DIN 7985)
30	1	343398020	Guard lever
31	1	342021920	Spring left
32	1	331050820	Parallel guide
33	1	343396920	Exhaust nozzle
34	1	343394770	Pressure plate
35	1	343394790	Switch slide
36	1	342021670	Spring clip
37	1	344097060	Rubber plug
38	1	141119960	Truss head screw
39	1	341703830	Fillister head screw M 6X40
40	2	341100970	Thumb-nut
41	2	141150960	Washer

42	1	141116050	Truss head screw
43	1	341111920	Thumbscrew
44	1	141150020	Washer
45	1	342003240	Pressure spring
46	1	141113200	Fillister head screw
47	1	141130070	Hexagonal nut
48	1	316037290	Guide plate cpl.
49	1	344161530	Hexagonal key
50	1	338121750	Warning Label serial 40x14
1001	1	338504870	Wiring diagram

