


Position	Amount	Type number	Description
1	1	316037790	Saw guide
2	1	339132250	Circlip
3	1	344096990	Insulation cover
4	1	341057530	Excentric setting ring
5	1	342021890	Spring left
6	2	341703770	Tap tite screw TORX 20 x 10
7	1	339132210	Retraining sheet
8	4	341703760	Tight fit srew Torx 20 x 58
9	1	344097010	Rubber packing
10	2	341703720	Screw
11	1	315104370	Gear Cover
12	2	344070820	Felt ring
13	3	320050530	Ball bearing, 15x32x9
14	2	339132230	Retaining ring
15	1	341057510	Spacer
16	1	339132240	Retaining ring
17	1	341090030	Wobble assy
18	1	341057490	Suppor+D15097t sleeve
19	1	341057550	Ball w. recess
20	1	341057540	Ram
21	2	320050520	Ball bearing, 8x22x7
22	1	341057520	Drive shaft
23	1	340012450	Spur gear
24	1	343390600	Handle with cover
25	6	341703730	Screw TORX 20 x 18
26	1	343407620	Switch 120 V
27	1	343390620	Pressure lever cpl.
28	1	342021910	Spring left
29	1	316037810	Guide lever
30	1	341520090	Tigthening pin
31	1	344070810	Felt ring
32	1	339006820	Washer
33	1	339132220	Guide locking plate
34	2	341703550	Allen head screw
35	1	341703710	Screw w. Bearing pin
36	1	399999990	Part not needed
38	2	338118620	Metabo plate
39	1	399999990	Part not needed
40	1	316037840	Brush set cpl. 120/230 V
41	4	341703740	Plastiite screw TORX 20 X 18
42	1	344070830	Felt ring

43	3	341703780	Tap tite screw TORX 20 x 9
44	1	330001660	Fan
45	1	310008710	Armature cpl. 120 V
46	1	344097040	Rubber bushing
47	1	342050790	Spring
48	1	315202250	Intermediate flange
49	1	320050540	Ball bearing, 10x26x8
50	1	344070840	Felt ring
51	1	316037800	Oscillating switch
53	2	341703680	Srew 5,3x50 TX 20
54	1	311010340	Field coil assembly w.field coil,120V
55	1	338045590	NAME PLATE
56	1	343390590	Motor housing
57	2	339011470	Holder insulation
58	1	343390690	FET holder
59	2	341147750	Plastic strip
60	1	343050180	Terminal rail
61	1	343390610	Guide plate
62	4	341703750	Screw TORX 20 x 25
63	1	344490960	Cable with plug
64	1	344097030	Cable sleeve
65	1	399999990	Part not needed
66	1	399999990	Part not needed
67	1	399999990	Part not needed
68	1	399999990	Part not needed
69	2	343000890	Brush holder
880	1	344131110	Grease 100Gr
1001	1	338504230	Diagram



WIRING DIAGRAM
120V VARIABLE SPEED
GROUP 1