



14.1.1 HVBS-710SG Table and Stand Assembly – Exploded View



14.1.2 HVBS-710SG Bow Assembly – Exploded View



14.1.3 HVBS-710SG Assembly – Parts List

| Index No. | Part No. | Description | Size | Qty |
|------------------|--------------------|-----------------------------|----------------|------------|
| 1..... | HVBS710S-1 | Bottom Pan..... | | 1 |
| 1-1..... | TS-0060071 | Hex Cap Screw..... | 3/8" x 1-1/2" | 2 |
| 1-2 | TS-0570031 | Hex Nut | 3/8" | 2 |
| 1-3..... | HVBS710S-1-3 | Support Post..... | | 1 |
| 1-4..... | TS-0720071 | Spring Washer | 1/4" | 2 |
| 1-5..... | TS-0050021 | Hex Cap Screw | 1/4" x 5/8" | 2 |
| 2..... | HVBS710S-2 | Feet-Stand (Right)..... | | 1 |
| 3..... | HVBS710S-3 | Feet-Stand (Left)..... | | 1 |
| 4..... | HVBS710S-4 | Panel..... | | 2 |
| 5..... | HVBS710S-5 | Clear Hose | 1" | 1 |
| 6..... | HVBS710S-6 | Pump | 1/8HP 1PH..... | 1 |
| 8..... | TS-0050011 | Hex Cap Screw | 1/4" x 1/2" | 4 |
| 9..... | HVBS710S-9 | Hose Fitting | | 1 |
| 10..... | HVBS710S-10 | Hose Clamp | | 1 |
| 11..... | HVBS710S-11 | Hose | 5/16" | 1 |
| 12..... | HVBS710S-12 | Coolant Tank | 9L..... | 1 |
| 13..... | HVBS710S-13 | Handle..... | | 1 |
| 14..... | TS-0081031 | Hex Cap Screw | 5/16" x 3/4" | 4 |
| 15..... | TS-0680031 | Flat Washer | 5/16" | 4 |
| 15-1..... | TS-0720081 | Spring Washer | 5/16" | 4 |
| 16..... | HVBS710S-16 | Wheel..... | 8" | 2 |
| 16-1..... | TS-0680061 | Flat Washer | 1/2" | 2 |
| 18..... | HVBS710S-18 | Axle | | 1 |
| 19..... | HVBS710S-19 | Cotter Pin | | 2 |
| 20..... | TS-0051071 | Hex Cap Screw | 5/16" x 1-1/2" | 4 |
| 21..... | TS-0680031 | Flat Washer | 5/16" | 8 |
| 21-1..... | TS-0720081 | Spring Washer | 5/16" | 4 |
| 22..... | TS-0561021 | Hex Nut | 5/16" | 4 |
| 23..... | HVBS710S-23 | Door | | 1 |
| 24..... | HVBS710S-24 | Pin | | 2 |
| 25..... | HVBS710S-25 | Lock Knob | 1/4" x 3/4" | 1 |
| 26..... | HVBS710S-26 | Filter | | 1 |
| 27..... | HVBS710S-27 | Bracket | | 1 |
| 28..... | HVBS710S-28 | Bracket | | 1 |
| 29..... | HVBS710S-29 | Chip Guide Plate | | 1 |
| 30..... | TS-0081031 | Hex Cap Screw | 5/16" x 3/4" | 2 |
| 31..... | TS-0561021 | Hex Nut | 5/16" | 2 |
| 31-1..... | TS-0720081 | Spring Washer | 5/16" | 2 |
| 32..... | TS-0680031 | Flat Washer | 5/16" | 2 |
| 32-1..... | TS-0081051 | Hex Cap Screw | 5/16" x 1" | 2 |
| 33..... | TS-0720081 | Spring Washer | 5/16" | 2 |
| 34..... | TS-0561021 | Hex Nut | 5/16" | 2 |
| 35..... | HVBS710S-35 | Lower Disc | | 1 |
| 36..... | TS-1505021 | Socket Head Cap Screw | M10 x 20 | 4 |
| 37..... | HVBS710S-37 | Swivel Base | | 1 |
| 43..... | HVBS710S-43 | Bottom Support | | 1 |
| 44..... | TS-0081051 | Hex Cap Screw | 5/16" x 1" | 3 |
| 45..... | TS-0720081 | Spring Washer | 5/16" | 3 |
| 46..... | HVBS710S-46 | Support Rod | | 1 |
| 47..... | HVBS710S-47 | Hydraulic Cylinder | | 1 |
| 48..... | HVBS710S-48 | Cylinder Cover | | 1 |
| 49..... | HVBS710S-49 | Round Head Screw | 1/4" x 1/2" | 2 |
| 50..... | HVBS710S-50 | Support Plate | | 1 |
| 51..... | TS-0060051 | Hex Cap Screw | 3/8" x 1" | 2 |
| 52..... | TS-0720091 | Spring Washer | 3/8" | 2 |


| Index No. | Part No. | Description | Size | Qty |
|------------------|-----------------|-----------------------|----------------|------------|
| 53 | TS-1492041 | Hex Cap Screw | M12 x 40 | 1 |
| 54 | TS-1540081 | Hex Nut | M12 | 1 |
| 55 | HVBS710S-55 | Splash Guard | | 1 |
| 56 | TS-0081031 | Hex Cap Screw | 5/16" x 3/4" | 2 |
| 57 | TS-0720081 | Spring Washer | 5/16" | 2 |
| 59 | TS-2311181 | Hex Nut | M18 x 2.5 | 2 |
| 60 | HVBS710S-60 | Washer | | 2 |
| 61 | HVBS710S-61 | Bushing | Ø22 x 28 x 7mm | 1 |
| 62 | HVBS710S-62 | Pivot Shaft | 22mm | 1 |
| 63 | HVBS710S-63 | Pivot Arm | | 1 |
| 64 | TS-0561021 | Hex Nut | 5/16" | 1 |
| 65 | TS-0051071 | Hex Cap Screw | 5/16" x 1-1/2" | 1 |
| 66 | TS-0570031 | Hex Nut | 3/8" | 1 |
| 67 | TS-0060081 | Hex Cap Screw | 3/8" x 1-3/4" | 1 |
| 68 | HVBS710S-68 | Plate | | 1 |
| 69 | TS-0060071 | Hex Cap Screw | 3/8" x 1-1/2" | 2 |
| 70 | TS-0720091 | Spring Washer | 3/8" | 2 |
| 72 | HVBS710S-72 | Upper Disc | | 1 |
| 73 | TS-1505021 | Socket Head Cap Screw | M10 x 20 | 4 |
| 74 | HVBS710S-74 | Lock Handle | 3/8" x 50mm | 1 |
| 75 | HVBS710S-75 | Bronze Bushing | | 1 |
| 76 | HVBS710S-76 | Thrust Shaft | | 1 |
| 77 | HVBS710S-77 | Scale | | 1 |
| 77-1 | HVBS710S-77-1 | Rivet | 2.3 x 4 mm | 2 |
| 78 | HVBS710S-78 | Angle Indicator | | 1 |
| 78-1 | HVBS710S-77-1 | Rivet | 2.3 x 4 mm | 1 |
| 81 | HVBS710S-81 | Table | | 1 |
| 82 | HVBS710S-82 | Handwheel Assembly | | 1 |
| 83 | TS-0270031 | Set Screw | 5/16" x 3/8" | 1 |
| 84 | HVBS710S-84 | Lead Screw | | 1 |
| 85 | HVBS710S-85 | Key | 5 x 20mm | 1 |
| 86 | HVBS710S-86 | Lead Screw Bracket | | 1 |
| 87 | HVBS710S-87 | Acme Nut | | 1 |
| 88 | HVBS710S-88 | Button | | 1 |
| 89 | HVBS710S-89 | Retainer | | 1 |
| 90 | TS-2361051 | Spring Washer | M5 | 1 |
| 91 | HVBS710S-91 | Round Head Screw | M5 x 8 | 1 |
| 92 | TS-1506031 | Socket Head Cap Screw | M12 x 30 | 2 |
| 93 | TS-0720111 | Spring Washer | 1/2" | 2 |
| 94 | HVBS710S-94 | Top Support | | 1 |
| 95 | TS-0081031 | Hex Cap Screw | 5/16" x 3/4" | 2 |
| 96 | TS-0720081 | Spring Washer | 5/16" | 2 |
| 97 | HVBS710S-97 | 90° Support | | 1 |
| 98 | TS-1491061 | Hex Cap Screw | M10 x 40 | 1 |
| 99 | TS-1540071 | Hex Nut | M10 | 1 |
| 100 | TS-0720091 | Spring Washer | 3/8" | 2 |
| 101 | TS-0060061 | Hex Cap Screw | 3/8" x 1-1/4" | 2 |
| 102 | HVBS710S-102 | Limit Switch | | 1 |
| 103 | HVBS710S-103 | Limit Switch Cover | | 1 |
| 104 | HVBS710S-104 | Hex Cap Screw | 3/16" x 3/8" | 2 |
| 105 | TS-0081051 | Hex Cap Screw | 5/16" x 1" | 1 |
| 106 | TS-0680031 | Flat Washer | 5/16" | 1 |
| 107 | HVBS710S-107 | Thumb Screw | | 1 |
| 108 | HVBS710S-108 | Stop Bracket | | 1 |
| 109 | HVBS710S-109 | Work Stop | | 1 |
| 110 | TS-0561021 | Hex Nut | 5/16" | 1 |
| 111 | TS-0081051 | Hex Cap Screw | 5/16" x 1" | 1 |

| Index No. | Part No. | Description | Size | Qty |
|------------------|----------------------|-------------------------------------|---------------------------|------------|
| 112 | HVBS710S-112 | Stop Rod | | 1 |
| 114 | TS-1492031 | Hex Cap Screw | M12 x 35 | 2 |
| 115 | TS-0720111 | Spring Washer | 1/2" | 2 |
| 116 | HVBS710S-116 | Fixed Vise | | 1 |
| 117 | TS-0060071 | Hex Cap Screw | 3/8" x 1-1/2" | 1 |
| 118 | TS-0720091 | Spring Washer | 3/8" | 2 |
| 119 | HVBS710S-119 | Hexagonal Stud | | 1 |
| 120 | TS-0680041 | Flat Washer | 3/8" | 1 |
| 121 | HVBS710S-121 | Floating Vise | | 1 |
| 122 | TS-0570031 | Hex Nut | 3/8" | 2 |
| 123 | TS-0060031 | Hex Cap Screw | 3/8" x 3/4" | 1 |
| 124 | HVBS710S-124 | Spring Bracket | | 1 |
| 125 | HVBS710S-125 | Spring Adjusting Rod | 3/8" | 1 |
| 126 | HVBS710S-126 | Spring | | 1 |
| 127 | HVBS710S-127 | Saw Bow | | 1 |
| 127-1 | TS-0051061 | Hex Cap Screw | 5/16" x 1-1/4" | 4 |
| 127-2 | TS-0720081 | Spring Washer | 5/16" | 4 |
| 127-3 | TS-0267042 | Socket Set Screw | 1/4" x 3/8" | 2 |
| 128 | TS-1503051 | Socket Head Cap Screw | M6 x 20 | 5 |
| 129 | HVBS710SG-129 | Vent Plug | | 1 |
| 130 | HVBS710S-222 | Key | 6 x 6 x 20 mm | 1 |
| 131 | TS-0060051 | Hex Cap Screw | 3/8" x 1" | 1 |
| 131-1 | TS-0720091 | Spring Washer | 3/8" | 1 |
| 131-2 | TS-0680041 | Flat Washer | 3/8" | 1 |
| 133 | HVBS710S-133 | Drive Wheel | | 1 |
| 134 | | Blade (local purchase) | 3/4" x 0.032" x 93" | 1 |
| 135 | HVBS710S-135 | Blade Back Cover | | 1 |
| 136 | HVBS710S-136 | Wheel Cover | | 1 |
| 137 | HVBS710S-137 | Knob | | 2 |
| 137-1 | TS-0680021 | Flat Washer | 1/4" | 2 |
| 138 | TS-0680021 | Flat Washer | 1/4" | 2 |
| 139 | HVBS710S-139 | Round Head Screw | 1/4" x 1/2" | 2 |
| 140 | HVBS710S-140 | Adjustable Guide Knob | 3/8" x 1-1/4" | 2 |
| 141 | HVBS710S-141 | Adjustable Bracket (Rear) | | 1 |
| 142 | BB-608ZZ | Ball Bearing | 608ZZ | 2 |
| 143 | HVBS710S-143 | Bearing Pin | 8 mm | 2 |
| 144 | HVBS710S-144 | Adjustable Blade Seat (Rear) | | 1 |
| 144-1 | HVBS710S-144-1 | Adjustable Blade Seat (Front) | | 1 |
| 145 | TS-0561032 | Hex Nut | 3/8"-24UNF | 4 |
| 145-1 | TS-0720091 | Spring Washer | 3/8" | 4 |
| 146 | HVBS710S-146 | Eccentric Shaft Assembly | | 2 |
| 146-1 | HVBS710S-146-1 | Center Shaft Assembly | | 2 |
| 147 | HVBS710S-147 | Vertical Cutting Plate | | 1 |
| 147-1 | HVBS710S-147-1 | Seat Plate | | 1 |
| 147-2 | TS-081F031 | Flat Head Screw | 1/4" x 1/2" | 2 |
| 152 | HVBS710S-152 | Top Support | | 1 |
| 153 | HVBS710S-153 | Hex Cap Screw | 3/8" x 1-1/4" | 2 |
| 154 | TS-0720091 | Spring Washer | 3/8" | 2 |
| 155 | TS-0570031 | Hex Nut | 3/8" | 2 |
| 156 | HVBS710S-139 | Round Head Screw | 1/4" x 1/2" | 2 |
| 157 | TS-0680021 | Flat Washer | 1/4" | 2 |
| 158 | HVBS710S-158 | Brush Holder | | 1 |
| 159 | TS-0267021 | Socket Set Screw | 1/4" x 1/4" | 1 |
| 160 | HVBS710S-160 | Fixed Bushing | | 1 |
| 161 | HVBS710S-161 | Brush | 1-1/2" x 6 mm | 1 |
| 162 | HVBS710S-162 | Support Rod | | 1 |
| 163 | HVBS710S-163 | Nozzle Cock | | 2 |

| Index No. | Part No. | Description | Size | Qty |
|------------------|----------------------|-------------------------------------|----------------|------------|
| 164 | HVBS710S-164 | Nozzle Cock Support..... | | 2 |
| 165 | TS-0267051 | Socket Set Screw..... | 1/4" x 1/2" | 2 |
| 166 | HVBS710S-166 | Socket Head Cap Screw..... | 5/16" x 1-1/8" | 2 |
| 166-1 | TS-0720081 | Spring Washer | 5/16" | 2 |
| 167 | HVBS710S-167 | Connection Tube | | 1 |
| 168 | HVBS710S-168 | Hose | | 1 |
| 169 | HVBS710S-169 | Hose | | 1 |
| 170 | HVBS710S-170 | Valve..... | | 2 |
| 171 | HVBS710S-171 | Hose Clamp..... | | 5 |
| 172 | HVBS710S-172 | Bracket..... | | 1 |
| 172-1 | TS-0050011 | Hex Cap Screw | 1/4" x 1/2" | 1 |
| 172-2 | TS-0720071 | Spring Washer | 1/4" | 1 |
| 172-3 | TS-0680021 | Flat Washer | 1/4" | 1 |
| 173 | HVBS710S-173 | Adjustable Bracket (Front) | | 1 |
| 174 | HVBS710S-174 | Blade Guard | | 1 |
| 175 | HVBS710S-175 | Round Head Screw | 3/16" x 1/4" | 2 |
| 176 | HVBS710S-176 | Sliding Guide Plate..... | | 2 |
| 177 | TS-0050011 | Hex Cap Screw | 1/4" x 1/2" | 4 |
| 178 | HVBS710S-178 | Blade Tension Sliding Block..... | | 1 |
| 179 | TS-0270071 | Socket Set Screw..... | 5/16" x 3/4" | 1 |
| 180 | TS-0051071 | Hex Cap Screw | 5/16" x 1-1/2" | 2 |
| 181 | HVBS710S-181 | Sliding Draw Block | | 1 |
| 182 | HVBS710S-182 | Bearing Bushing..... | | 1 |
| 183 | BB-6203ZZ | Ball Bearing | 6203ZZ | 2 |
| 184 | HVBS710S-184 | Idler Wheel | | 1 |
| 185 | TS-0680031 | Flat Washer | 5/16" | 1 |
| 185-1 | TS-0720081 | Spring Washer | 5/16" | 1 |
| 186 | TS-0081031 | Hex Cap Screw | 5/16" x 3/4" | 1 |
| 187 | TS-0680041 | Flat Washer | 3/8" | 1 |
| 188 | HVBS710S-188 | Blade Tension Handle | | 1 |
| 189 | HVBS710S-189 | Support Plate | | 1 |
| 190 | TS-0680021 | Flat Washer | 1/4" | 2 |
| 191 | TS-0050011 | Hex Cap Screw | 1/4" x 1/2" | 2 |
| 192-1 | HVBS710SG-192-1..... | Motor..... | 1HP 1PH | 1 |
| | HVBS710SG-192-MF | Motor Fan (not shown)..... | | 1 |
| | HVBS710SG-192-MFC | Motor Fan Cover (not shown)..... | | 1 |
| | HVBS710SG-192-JB | Junction Box..... | | 1 |
| | HVBS710SG-192-JBC | Junction Box Cover | | 1 |
| 192-2 | HVBS710SG-192-2..... | Strain Relief | | 1 |
| 192-3 | TS-1490031 | Hex Cap Screw | M8x20 | 2 |
| 192-4 | TS-2361081 | Spring Washer | 8 mm | 2 |
| 193 | HVBS710S-193 | Key | 5 mm | 1 |
| 194-1 | HVBS710SG-328..... | Worm Shaft | | 1 |
| 195-1 | HVBS710SG-195-1..... | Gear Flange | | 1 |
| 195-2 | TS-1503051 | Socket Head Cap Screw | M6x20 | 1 |
| 196-1 | HVBS710SG-196-1..... | Gear Box Assembly | | 1 |
| 197 | HVBS710S-197 | Splash Guard (Front)..... | | 1 |
| 198 | TS-0680021 | Flat Washer | 1/4" | 2 |
| 199 | TS-0720071 | Spring Washer | 1/4" | 2 |
| 200 | TS-0050011 | Hex Cap Screw | 1/4" x 1/2" | 2 |
| 201 | HVBS710S-201 | Control Box..... | | 1 |
| | HVBS710S-250 | Magnetic Contactor (not shown)..... | | 1 |
| 202 | HVBS710S-202 | Strain Relief Fitting | | 4 |
| 203 | HVBS710S-203 | Control Panel | | 1 |
| 204 | HVBS710S-204 | Round Head Screw | 3/16" x 3/8" | 6 |
| 205 | HVBS710S-205 | Start Switch | | 1 |
| 206 | HVBS710S-206 | Stop Switch | | 1 |
| 207 | HVBS710S-207 | Emergency Stop Switch..... | | 1 |

| Index No. | Part No. | Descriptions | Size | Qty |
|------------------|---------------------|--|-------------|------------|
| 208 | TS-0050031 | Hex Cap Screw | 1/4" x 3/4" | 2 |
| 209 | HVBS710S-WL..... | Warning Label (not shown) | | 1 |
| 210 | HVBS710S-LBDA | Label – Blade Direction Arrow (not shown)..... | | 1 |
| 211 | HVBS710SG-ID | I.D. Label (not shown) | | 1 |
| | HVBS710S-HP | Hardware Package (see contents page 8)..... | | 1 |
| | JETLOGO-1 | JET Logo..... | 2-3/4" x 8" | 1 |
| | STRIPE-1-3/4 | JET Stripe..... | 1-3/4" | per ft. |

14.2.1 HVBS-710SG Gearbox Assembly – Exploded View



14.2.2 HVBS-710SG Gearbox Assembly – Parts List

| Index No. | Part No. | Description | Size | Qty |
|------------------|-----------------|-------------------------------------|----------------|------------|
| | HVBS710SG-196-1 | Gearbox Assembly (index #1 thru 42) | | 1 |
| 1 | HVBS710SG-129 | Vent Plug | | 1 |
| 2 | TS-1503051 | Socket Head Cap Screw | M6 x 20 | 5 |
| 3 | HVBS710SG-303 | Gear Box Cover | | 1 |
| 4 | HVBS710SG-304 | Gasket | | 1 |
| 5 | HVBS710SG-305 | Drive Gear Assembly | | 1 |
| 6 | HVBS710SG-306 | Drive Shaft | | 1 |
| 7 | HVBS710SG-307 | Key | 5 x 80 mm | 1 |
| 8 | HVBS710SG-308 | C-Ring | S-25 | 3 |
| 9 | BB-6205 | Ball Bearing | 6205 | 2 |
| 10 | BB-6201 | Ball Bearing | 6201 | 5 |
| 12 | HVBS710SG-312 | Transfer Gears Assembly | | 1 |
| 14 | HVBS710SG-314 | Socket Head Cap Screw | M5 x 15 | 1 |
| 15 | HVBS710SG-315 | Adjustable Bracket | | 1 |
| 16 | HVBS710SG-316 | Key | 6 x 18 mm | 1 |
| 17 | HVBS710SG-317 | Bushing | | 1 |
| 18 | HVBS710SG-318 | Drain Plug | | 1 |
| 20 | HVBS710SG-320 | Worm Gear | | 1 |
| 21 | HVBS710SG-321 | Input Gears | | 1 |
| 24 | HVBS710SG-324 | Motor Cover | | 1 |
| 26 | HVBS710SG-326 | Set Pin | 6 x 15 mm | 2 |
| 27 | HVBS710SG-327 | O-Ring | G60 | 1 |
| 28 | HVBS710SG-328 | Worm Shaft | | 1 |
| 29 | HVBS710SG-329 | Gear Flange | | 1 |
| 30 | TS-1503051 | Socket Head Cap Screw | M6 x 20 | 1 |
| 31 | HVBS710SG-331 | Gear Box | | 1 |
| 32 | HVBS710SG-332 | Oil Seal | 30 x 42 x 7 mm | 1 |
| 33 | HVBS710SG-333 | Indicator Plate | | 1 |
| 34 | TS-2284081 | Flat Head Screw | M4 x 8 | 3 |
| 35 | SB-1/4 | Steel Ball | 1/4" | 1 |
| 36 | HVBS710SG-336 | Compression Spring | 1/4" | 1 |
| 37 | HVBS710SG-337 | Plastic Handle | | 1 |
| 38 | HVBS710SG-338 | O-Ring | 7 x 1.5 mm | 1 |
| 39 | HVBS710SG-339 | Axle | | 1 |
| 40 | HVBS710SG-340 | Set Pin | 3 x 20 mm | 1 |
| 41 | TS-1490031 | Hex Cap Screw | M8 x 20 | 2 |
| 42 | TS-2361081 | Spring Washer | 8 mm | 2 |

15.0 Electrical Connections for HVBS-710SG

