



WIRING SPECIFICATIONS			
Wire No.	Wire Color	Origin or Part No.	Terminals, Connectors and End Wire Preparation
1	White	22-64-1080	Component of the cord set. Connect to J2 on Bay 3.
2	Black	22-64-1080	Component of the cord set. Connect to J1 on Bay 3.
3	Black	23-94-1315	Component of the leadwire assembly. Connect to J7 on Bay 3 / Connect to J1 on Bay 2.
4	White	23-94-1210	Component of the leadwire assembly. Connect to J8 on Bay 3 / Connect to J2 on Bay 2.
5	Black	23-94-1315	Component of the leadwire assembly. Connect to J7 on Bay 2 / Connect to J1 on Bay 1.
6	White	23-94-1210	Component of the leadwire assembly. Connect to J8 on Bay 2 / Connect to J2 on Bay 1.
7	Red	23-74-1525	Component of the battery connector assembly. 3 assemblies. Connect to J3 on corresponding Bays 1, 2 and 3.
8	White	23-74-1525	Component of the battery connector assembly. 3 assemblies. Connect to J5 on corresponding Bays 1, 2 and 3.
9	Black	23-74-1525	Component of the battery connector assembly. 3 assemblies. Connect to J6 on corresponding Bays 1, 2 and 3.
10	Red	23-28-0135	Component of the LED/Lens. 3 assemblies. Service according to the instructions above.
11	White	23-28-0135	Component of the LED/Lens. 3 assemblies. Service according to the instructions above.
12	Green	23-28-0135	Component of the LED/Lens. 3 assemblies. Service according to the instructions above.
BULK LEAD WIRE - BULLETIN 58-01-0003			