


# PS 50



**1.1991**

**Spare parts**


**Ersatzteile**

**Pièces détachées**


**Repuestos**



**Reservdelar**

**A**





**B**







**E** \* compl 502 06 40-01




F

\* compl 502 26 30-01




# H

\* compl 502 41 20-01




# O

**Accessories  
 Zubehöre  
 Accessoires  
 Accesorios  
 Tillbehör**






J



M

compl 502 40 05-01











\* compl 502 41 00-01





**N** \* compl 503 28 10-16

### Walbro HDA-86 A



P

Delivery as spare part only  
Nur als Ersatzteil lieferbar  
Livvable seulement comme pièce de rechange  
Solo como repuesto  
Leveras endast som reservdel



MODEL NUMBER PS50

PARTNUMBER	SQUARE	NOTE	PARTNUMBER	SQUARE	NOTE	PARTNUMBER	SQUARE	NOTE	PARTNUMBER	SQUARE	NOTE
501 26 97-02	G,M		502 17 47-01	A		502 41 24-01	G		503 49 69-01	A	
501 45 16-01	C		502 17 81-01	F		502 41 25-01	G		503 54 39-01	F	
501 45 61-01	G		502 20 30-11	K		502 41 29-02	G		503 56 21-01	N	
501 46 07-02	K		502 22 71-02	A		502 41 30-02	G		503 56 23-01	N	
501 46 57-01	J		502 25 29-01	A		502 41 31-01	G		503 56 25-01	N	
501 46 84-01	N		502 25 40-01	L		502 41 34-02	G		503 56 34-01	N	
501 46 86-01	N		502 25 45-01	N		502 41 35-01	G		503 57 42-01	N	
501 46 87-01	N		502 25 46-01	N		502 41 36-01	G		503 58 15-01	N	
501 48 54-02	J		502 25 47-01	N		502 41 37-01	G		503 59 63-01	N	
501 48 92-01	J		502 26 30-01	F		502 41 38-01	G		503 61 48-01	N	
501 53 16-01	J		502 40 03-05	K		502 41 41-01	G		504 02 72-12	N	
501 54 15-02	J		502 40 04-04	G		502 41 48-01	L		504 02 72-13	N	
501 59 41-01	M		502 40 05-01	M		502 41 49-01	H		504 13 09-05	N	
501 66 61-01	N		502 40 39-01	K		502 41 56-03	G		504 21 00-48	N	
501 66 62-01	N		502 40 42-01	K		502 41 59-01	G		504 86 04-08	N	
501 66 67-01	N		502 40 45-01	K		502 41 65-01	M		505 27 75-16	J	
501 66 69-01	N		502 40 46-01	K		502 41 69-01	M		505 30 51-25	F	
501 66 73-01	N		502 40 47-02	K		502 41 71-01	M		505 31 55-44	G	
501 66 77-01	N		502 40 49-01	K		502 41 74-01	O		505 31 67-17	N	
501 66 78-01	N		502 40 50-01	K		502 41 91-02	K		505 52 01-25	N	
501 66 83-01	N		502 40 52-01	K		502 41 97-01	M		506 02 72-01	J	
501 66 84-01	N		502 40 59-01	K		502 42 03-01	M		506 02 83-01	N	
501 67 67-02	C		502 40 60-01	K		502 42 04-01	O		506 02 94-01	K	
501 68 89-01	O		502 40 61-01	K		502 42 06-01	G		720 13 07-10	H	
501 69 17-01	O		502 40 63-01	K		502 42 07-01	G		722 78 07-02	A,L	
501 79 59-01	N		502 40 65-12	K		502 42 07-02	G		723 13 31-01	L	
501 86 20-02	A		502 40 65-13	K		502 42 15-01	P		725 52 92-55	H	
501 86 21-02	C		502 40 65-14	K		502 42 16-01	P		725 52 95-56	J	
501 86 25-02	A		502 40 65-15	K		502 42 17-01	P		725 53 27-56	D	
502 00 21-04	F		502 40 65-16	K		502 42 18-01	K		725 53 29-01	A,F	
502 03 47-01	D		502 40 69-01	G		502 42 19-01	G		725 53 29-55	G	
502 03 56-03	D		502 40 70-01	K		502 42 31-01	K		725 53 31-55	G	
502 03 59-01	D		502 40 71-01	G,K		502 42 32-01	K		725 53 32-55	C	
502 03 60-01	D		502 40 71-02	G		502 42 33-01	G		725 53 35-55	H	
502 03 86-03	F		502 40 71-03	G		502 42 35-02	K		725 53 43-55	H	
502 05 02-02	H		502 40 71-04	G,K		502 42 35-03	K		725 53 48-55	D	
502 05 05-03	H		502 40 72-16	K,P		502 42 35-04	K		725 63 25-55	K	
502 05 07-02	H		502 40 73-02	P		502 42 35-05	K		725 63 29-55	A	
502 05 24-05	A		502 40 74-02	K		502 42 35-06	K		729 22 23-01	F	
502 05 35-05	J		502 40 75-01	K		502 42 38-01	K		729 52 21-01	L	
502 05 42-01	J		502 40 84-01	O		502 42 43-01	F		729 52 26-71	L	
502 06 34-01	B		502 40 88-01	K		503 08 20-01	N		729 52 30-71	L	
502 06 40-01	E		502 40 88-02	K		503 09 83-02	L		731 23 14-01	L	
502 06 44-01	A,H		502 40 89-01	K		503 10 87-01	N		731 23 18-01	J	
502 06 93-03	G		502 40 89-02	G		503 15 82-01	H		732 21 14-01	L	
502 07 04-01	A		502 40 89-07	K		503 16 17-01	N		734 11 36-01	H	
502 10 02-02	A		502 40 89-08	K		503 20 00-02	F		734 11 36-41	L	
502 10 12-07	B		502 40 92-01	K		503 20 20-05	K		735 11 36-50	J	
502 10 18-01	B		502 40 93-01	K		503 20 40-20	O		735 11 64-50	J	
502 10 41-01	B		502 40 94-81	K		503 20 64-10	G,K,M		735 80 15-00	E	
502 10 41-02	B		502 41 00-01	L		503 20 64-16	K		737 44 10-00	C	
502 11 98-01	N		502 41 01-01	L		503 20 64-20	H		738 22 02-15	E	
502 14 44-01	L		502 41 02-01	L		503 20 65-10	G		950 26 71-09	O	
502 15 52-02	D		502 41 03-01	L		503 20 65-16	F				
502 15 56-01	D		502 41 04-01	L		503 20 70-16	G				
502 15 57-01	D		502 41 05-01	L		503 21 11-03	D				
502 17 05-02	M		502 41 06-01	L		503 22 21-02	G				
502 17 13-01	A		502 41 07-01	H		503 22 65-01	K				
502 17 16-01	A		502 41 09-01	L		503 22 65-03	F				
502 17 17-01	A		502 41 13-01	A		503 22 66-01	K				
502 17 19-02	A		502 41 14-01	F		503 23 00-05	J				
502 17 20-02	F		502 41 15-01	J		503 23 00-10	D				
502 17 21-01	F		502 41 16-01	L		503 23 00-35	H				
502 17 25-01	A		502 41 17-01	L		503 23 50-11	C				
502 17 25-02	P		502 41 18-01	L		503 26 02-04	H				
502 17 28-02	F		502 41 19-01	L		503 28 10-16	A,N				
502 17 33-02	H		502 41 20-01	H		503 28 90-10	C				
502 17 37-01	C		502 41 21-01	L		503 30 31-32	K				
502 17 39-01	C		502 41 22-01	F		503 44 32-01	F				
502 17 45-01	A		502 41 23-01	G		503 44 77-01	D				