


Vac Attack II Blower UT-08514 - Figure A



Ref #	Part #	Description	Qty	Context Note
1	518251001	Blower Shroud	1	
2	900954001	Crankcase Gasket	1	
3	638031001	Crankcase Cover	1	
4	660664001	Screw (10-24 X 9/16 in Pan Hd.)	4	Purchase locally
5	650017001	Flat Washer	1	
6	650018001	Fan Spacer	2	
7	660669001	Screw (#8 X 1/2 in Pan Hd.)	6	Purchase locally
8	638032002	Baffle	1	
9	900957001	Baffle Gasket	1	
10	518098001	Pully	1	
11	638033001	Spring & Container	1	
12	650015001	Washer	1	
13	760363002	Switch	1	
14	518249001	Inner Volute Housing	1	
15	650013001	Bushing - Starter Rope	1	
16	518073001	Starter Grip	1	
17	650014001	Bushing	1	
18	900849004	Starter Rope	1	
19	660630002	Screw (10-24 X 3/4 in Truss Hd.)	4	Purchase locally
20	308088001	Primer Bulb	1	
21	660618001	Screw (10-14 X 1/2 in Torx Truss Hd.)	3	Purchase locally
22	308279003	Inner Housing & Starter Assembly	1	Inc Key Nos 7-11, 13-18
23	660629001	Screw (10-14 X 3/4 in Torx Truss Hd.)	6	Purchase locally
24	660667001	Screw (10 X 1-5/8 in Hex Hd.)	1	Purchase locally
25	348007001	Pin	1	
26	518211001	Slide	1	
27	518247001	Trigger	1	
28	650016001	Flat Washer	1	
29	518077001	Fan	1	
30	638074001	Wire Loop	1	
31	640858001	Fan Adaptor	1	
32	660730001	Lock Nut (3/8-24)	1	Purchase locally
33	518250001	Outer Volute	1	
34	518078001	Door	1	
35	660668001	Screw (1/4-20 X 3/4)	1	Purchase locally

Vac Attack II Blower UT-08514 - Figure B

HOMELITE YARD BROOM II - MODEL NUMBER UT08514




Figure B


Rendered by LeadVenture, Inc.

Ref #	Part #	Description	Qty	Context Note
1	300952002	Fly Wheel Assembly	1	
2	308128003	Crankcase Assembly	1	
3	290195004	Ignition & Switch Harness	1	
4	308023003	Piston & Rod Assembly	1	
5	660342002	Screw (M5 X 20 mm)	3	Purchase locally
6	660734001	Screw (M4 X 1.75 X 16 mm)	1	Purchase locally
7	300748010	Muffler Assembly	1	Inc Key Nos 8-13
8	678046001	Insulating Washer	1	
9	678045001	Flat Washer	1	
10	678044001	Compression Spring	1	
11	900994001	Muffler Gasket	1	
12	660673001	Screw (10-24 Hex Hd.)	2	Purchase locally
13	300748013	Muffler	1	
14	660660001	Screw (8-32 X1.0 in.)	2	Purchase locally
15	850080001	Ignition Module	1	
16	640069002	Cylinder	1	
17	900953001	Cylinder Gasket	1	
18	638133002	Throttle Cable Clip	1	
19	308192005	Short Block Assembly	1	Inc Key Nos 2, 4, 16 and 17
20	660345001	Screw (M4)	1	
21	590458001	Choke Lever	1	
22	590946001	Choke Plate	1	
23	900950001	Heat Dam Gasket	1	
24	660346002	Carburetor Mounting Bolt	2	
25	518087001	Heat Dam	1	
26	660662001	Screw (10-24 X 1.11 Pan Hd.)	2	Purchase locally
27	900951004	Carburetor Gasket	1	
28	518120001	Spacer	1	
29	900711003	Carburetor Gasket	1	
30	308429001	Carburetor (Walbro WYC-10)	1	
31	518493001	Air Filter Box	1	
32	678027001	Hex Nut (10-24)	1	Purchase locally
33	270021002	Throttle Cable	1	
34	308592001	Air Box Base Assembly	1	Inc Key Nos 20-22, 31 and also Inc Key Nos 5, and 12 On Page 2

Vac Attack II Blower UT-08514 - General Assembly

HOMELITE YARD BROOM II - MODEL NUMBER UT08514

The model number will be found on a plate attached to the engine housing. Always mention the model number in all correspondence regarding your **YARD BROOM II** or when ordering repair parts.



Rendered by LeadVenture, Inc.

Ref #	Part #	Description	Qty	Context	Note
1	580555001	Upper Blower Tube	1		
2	580556001	Wide Sweeper Nozzle	1		
3	348005003	Clamp Assembly	1		
4	870174001	Spark Plug	1		
5	560873001	Air Filter	1		
6	308890001	Air Box Cover Assembly	1	Inc Key No 5	
7	300758006	Fuel Cap Assembly	1		
8	940299487	Logo Label	1		
9	940642012	Starting Label	1		
10	940299493	Warning Label	1		
11	308141010	Fuel Tank & Cap Assembly	1	Inc Key No 7	
	983000927	Operator's Manual			